



SERVICE BULLETIN 02-3002

Contact: Mike Hankins, Director of Customer Relations
Mainship Corporation
mhankins@mainship.com

December 3, 2002

Models Affected: Pilot™30

Rudder bolt, installed into rudder through Sandshoe opening, could loosen and fall out of rudder.

All Pilot™30 models should be inspected for loosening of bolt.

Any boats in the field that have signs of loosening, after inspection of rudder assembly, should contact Customer Service for details and directions.

Questions should be directed to Customer Service department. Thanks for your assistance.

Mike Hankins
(904) 827-2025
(800) 578-0852