



SERVICE BULLETIN 02-3903

Contact: Mike Hankins, Director of Customer Relations
Mainship Corporation
mhankins@mainship.com

November 3, 2002

Models Affected: 39 Trawler

Swim platform may have water seeping into the foam of the platform module.

Any 39 Trawler with foam-filled swim platform construction should inspect hardware for proper sealing.

Any boats in the field that have signs of water entry, after inspection of underwater hardware, should contact Customer Service for details.

Questions can be communicated to Mainship Customer Service department. Thanks for your assistance.

Mike Hankins
(904) 827-2025
(800) 578-0852