



SERVICE BULLETIN 03-4302

Contact: Mike Hankins, Director of Customer Relations
Mainship Corporation
mhankins@mainship.com

June 30, 2003

Models Affected: 39/40/43 Trawlers

Fuel tanks may not have protective rubber pad on corner of fuel tank, near battery compartment/tray.
Contact of wrench to fuel tank, when tightening battery lugs, could cause fire hazard.

39 Trawler: Hull # 350-397

40 Trawler: Hull #103-112

43 Trawler: Hull#85-93

All above MUST be checked immediately to insure proper material is applied to the fuel tank as outlined in attached documentation. Attached picture is for 40 model. Pictures are available on each model if needed, all are similar. Approved labor for this function is 1 hour. Documentation of boats checked is required.

Questions should be directed to Customer Service department. Thanks for your assistance.

Mike Hankins
(904) 827-2025
(800) 578-0852

Order part number #A407340 RUBBER SHEET (1 Each)
1.88 sf • 15x15 • 1/8" self-adhesive rubber
parts@mainship.com • Fax: (912) 880-2124

