



SERVICE BULLETIN 02-4301

Contact: Mike Hankins, Director of Customer Relations
Mainship Corporation
mhankins@mainship.com

November 23, 2002

Models Affected: 43 Trawler

Port and Starboard sliding doors may allow water entry under rough sea conditions.

Any 43 Trawler with signs of water entry, or complaint by customer, should be immediately addressed.

Any boats in the field that have signs of water entry, after inspection of sliding door areas, should contact Customer Service for details and directions.

Questions can be communicated to Mainship Customer Service department. Thanks for your assistance.

Mike Hankins
(904) 827-2025
(800) 578-0852